



NTSB National Transportation Safety Board

Office of Aviation Safety

Colgan Air Flight 3407 Buffalo, New York

Case Study

John DeLisi

Director, Office of Aviation Safety

History of Flight

- February 12, 2009
- Colgan Air, Bombardier DHC-8-400
- Continental Connection flight 3407
 - Newark to Buffalo

- All 49 people on-board, 1 resident were killed



Accident Overview

- Inadvertent Low Speed Warning
- **Incorrect response from Captain**
 - Pulled back on Control Column (instead of pushing forward)
 - Airplane pitched up and lost control

Accident Animation



National Transportation Safety Board


22:16:16

157 knots **2260** feet Shaker **OFF** Pusher **OFF**

Power Condition Flap



Heading **253**°

L Pedal  R

Auto Pilot **ON**

Gear **DOWN**

Investigation Protocol

- NTSB Notified of Accident
- Go-team Assembled
 - Launched from DC at 6am
 - Two trips on FAA Gulfstream
 - FDR/CVR returned to DC
- Parties Notified

Parties to the Investigation

- Federal Aviation Administration
- Colgan Air, Inc.
- Air Line Pilots Association
- National Air Traffic Controllers Association
- United Steelworkers Union
(Flight Attendants)

Accredited Representatives

- Transportation Safety Board –
Canada
 - Transport Canada
 - Bombardier
 - Pratt & Whitney Canada
- Air Accidents Investigation Branch –
United Kingdom
 - Dowty Propellers

Organizational Meeting

- Overview of Site and Hazards
- Named Investigative Groups:
 - Operations, ATC, Meteorology
 - Powerplants, Systems, Structures
 - FDR/CVR, Maintenance
 - Aircraft Performance
 - Human Performance

Each Group Led By NTSB



On- Scene for Eight Days

- Focus on perishable info
- Progress Meetings
- Press Briefings, Family Briefings
- Wreckage recovered and stored

Post On- Scene Activities

- Interviews
- Teardowns
- Performance Study of FDR Data
- Investigative Public Hearing

Public Hearing

- May 12 – 14, 2009 in DC
- Sworn Testimony from 19 People
 - Colgan Directors of Training, Operations
 - FAA Principal Inspectors
 - NASA Aerodynamics Researchers

Wrap Up Activities

- Complete all Group Work
- Technical Review
- Party Submissions
- NTSB Staff Prepared Draft Report

Final Report of Investigation

- Board Meeting on February 2, 2010
 - Less than a year after the accident
- 46 Findings
- Probable Cause
- 25 Safety Recommendations

Key Findings

- Inappropriate control inputs
- Typical of startle and confusion
- Breakdown in flight monitoring, sterile cockpit rules
- Impairment due to fatigue

Probable Cause

- Inappropriate response to warning which led to stall aerodynamic stall
- Contributing factors:
 - failure to monitor airspeed
 - failure to adhere to sterile cockpit
 - inadequate procedures for airspeed selection in icing conditions.

Key Recommendations

- Leadership training for captains
- Fatigue mitigation – commuting pilots
- Airspeed selection procedure
- Stall recovery training



NTSB